TECHNICAL DATA SHEET

3D PRINT BED SURFACE CLEANER SPRAY



PROFESSIONAL CLEANING FOR PRINT BEDS

UFI
7000-W09U-Q009-TRXG

EAN-13
8411322300273

400 ml. ℮
13,52 fl.oz.

DEVELOPED AND MANUFACTURED IN
Spain / Europe

CLEAN3D is a professional cleaner specifically developed for the cleaning and maintenance of FDM/FFF 3D print surfaces.

Its isopropyl alcohol-based formula effectively removes adhesive residues, grease, fingerprints, dust and other common contaminants, leaving the print bed perfectly clean and ready for the next print.

Its fast-evaporating formula leaves no residue on the surface, helping maintain the print bed in optimal condition while promoting consistent adhesion throughout the printing process.

PHYSICAL PROPERTIES

Type	Hydroalcoholic solution
Color	Blue
Odor	Fragranced
Appearance	Clear blue liquid
Main component	Isopropyl alcohol
Purified water	Yes
Fragance	Yes
Colorants	CI42090 / CI17200
Shelf life	> 5 years
Application conditions	Cold print bed
Storage conditions	5–25 °C

APPLICATIONS

CLEAN3D can be used on most surfaces commonly found in FDM/FFF 3D printing to remove contaminants before starting a print.

Recommended for:

- **Glass**
- **Mirrors**
- **Smooth PEI**
- **Textured PEI**
- **Flexible steel sheets**
- **Aluminium**
- **Magnetic build plates**
- **Metal surfaces**
- **Other compatible surfaces***

*Always test on sensitive materials before use.

DIRECTIONS FOR USE

01 CLEAN. Ensure the print bed is completely cool before applying the product.
02 SPRAY. Spray a small amount directly onto the surface or onto a clean cloth.
03 WIPE. Spread the product evenly across the entire print bed.
04 DRY. Allow a few seconds for complete evaporation before starting the print.

BENEFITS

- **Removes adhesive residues**
- **Removes grease & oils**
- **Removes fingerprints**
- **Prepares the surface**
- **Residue free**
- **Easy to Apply**
- **Compatible with multiple print beds**
- **Ultra-fast drying**

PRECAUCIONES

Highly flammable liquid and vapor. Causes serious eye irritation. May cause drowsiness or dizziness. If medical advice is needed, have the product container or label at hand. Keep out of reach of children. Read and follow all instructions carefully. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Avoid breathing vapors. Use only outdoors or in a well-ventilated area. Do not ingest. Dispose of contents and container in accordance with local regulations.



Laboratorios 3D Print C/Los Olmos 6, 49600 Benavente-Zamora
Phone: +34 980 544 109 Mail: info@3dlac.com

3DLAC®